On-site Wastewater Section

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Lot #: 34
File #:
AppID:

Owner: Bobby Robinson
Address: Lot 34 Rotherwood Rd
Proposed Facility: Design Flow (.1949) 460
Location of Site:

Applicant:
Date Evaluated: 6/3/15
Property Size: 0.77 Ac
Property Recorded:

Water Supply: [ ] Public [✓] Individual [✓] Well [ ] Spring [ ] Other
Evaluation Method: [✓] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [✓] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY 1941 Structure/ Texture	SOIL MORPHOLOGY 1941 Consistence Mineralogy	b - PROFILE FACTORS 1942 Soil Wetness/ Color	1943 Soil Depth (IN.)	1956 Sapro Class	1944 Restr. Horiz	Profile Class & LTAR
AH 1	LS 4-6 %	0-2	gr l	fri nonp 1:1	NA	PS	NA	NA	0.3
		2-13	mod sbk cl	" ss sp "					
		13-48	wk sbk cl	" ss sp "					
2	LS just above cimbing 15	0-4	gr l	fri nonp 1:1	wetness below surface	"	"	"	0.3
		4-18	mod sbk cl	fri ss sp "					
		18-36	wk sbk cl	" " "					
		36-51	" "	" " "					
3	LS gentle slope 6%	0-4	gr l	fri nonp 1:1			Soil in Jap		few wd frags 0.3
		4-14	fine/med HWB cl	fri ss sp "					
		14-41	wk sbk cl	fri ss sp "					
		41-48	wk sbk cl	" nonp "					
4	LS 5-10%	0-4	gr l	fri nonp 1:1	low wetness below surface		PS		0.3
		4-17	mod sbk cl	fri ss sp "					
		17-45	"	" " "					
		45-53	mod sbk cl	fri nonp "					

Description	Initial System	Repair System
Available Space (.1945)	70	PS
System Type(s)	25% red	75 25% red
Site LTAR	0.3	0.3

Other Factors (.1946):
Soil Evaluation By: T Jacobs
Others Present:
Site Classification (.1948):
Site Evaluation By:
Others Present:

OK Tchd
APPROVED JUN 12 2015
SL