4637324390

13313

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Ray Lee Pinion DATE 4/6/92 PERMIT NO. 2K-6-A-218

PHONE: Business 474 Home 892-7128

LOCATION Oak Tree Rd, TR off Brawley School, TL to n 3/4 mile on (R) below road S.R. No. _____

SUBDIVISION NAME C L & T LOT NO. 218 SECTION OR BLOCK NO. 9

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 20,000 FT²

Soil Characteristics P - C / SC


Application Rate .35

Topography 20%

Depth to Water Table 48"

Rock or other impervious formations None observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2@130' X3'

Sq. Ft. 780 Linear Ft. 260

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐

Installed by Clint Dillard
HICKORY

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS _____

CERTIFICATE OF COMPLETION BY Wesley Sparkes DATE 4/6/92

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ray Lee Pinion DATE 8/23/91 PERMIT NO. 2K-6-A-218

PHONE: Business _____ Home 892-7128

LOCATION Oak Tree Rd, Brawley School TR Oak Tree, Lee (L) Statesville, Lot on (R) in 3/4 mile newly cleared S. R. No. _____

SUBDIVISION NAME CL+T LOT NO. 218 SECTION OR BLOCK NO. 9

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil P - cl - scl
Percolation Rate (.35) .4
Topography 4%
Depth to Water Table > 48"
Rock or other impervious formations None found

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2 @ 130' X 3'
Sq. Ft. 780 Linear Ft. 260
Depth of Stone in Lines 12"
Water Supply: Individual (✓) *
Public ( )
*50' FROM ALL PARTS OF SEPTIC TANK SYSTEM

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Ray Lee Pinion

IMPROVEMENTS PERMIT BY Wesley Sparks RS.

COMMENTS: This system to be shallow - no deeper than 30" to trench bottom. Trenches must follow slope contours in manner shown here. Special efforts must be made to divert surface water off this drainfield

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold