DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Robert & Susan Dewey
ADDRESS: oak Tree Rd. Lot 224
PROPOSED FACILITY: New Home PROPOSED DESIGN FLOW (.1949): 360
LOCATION OF SITE: Brawley Sch. Rd. W, TR oak Tree Rd, on right
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut

APPLICATION DATE _____
DATE EVALUATED: 7-29-05
PROPERTY SIZE: .66 AC
PROPERTY RECORDED: Prior to 1983
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	16% linear	0-34	1 sbk cl	Fr ss/sp se					.3 PS
		34-48	l + sap						
2		0-12	1 sbk cl	Fr ss/sp se					.3 PS
		12-38	1 sbk c	Fr ss/sp se					
		38-48+	l + sap						
3	4%	0-28	1 sbk/abk c						.3 PS
		28	c + sap						
4	pit	0-48+	1 sbk c						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	Panel PM	LP Panel
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Judy Melville
OTHER(S) PRESENT: Tom Coregory

COMMENTS: 1949 d sand mnd trench