08992

4637443382

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR James Doug Brown DATE 6/5/89 ~~PERMIT~~ NO. 21A

PHONE: Business _____ Home _____

LOCATION 150 W. TL 1180 (Doolie Road) TR Whippoorwill ~ 1/4 mile on left S. R. No. _____

SUBDIVISION NAME C L and T LOT NO. 19 SECTION OR BLOCK NO. 10

House ( ) Mobile Home ( ) Business ( ) Other Replacing M.H. w/home.


No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit	Yes	(✓)	No	( )	
Auto. Dishwasher	Yes	(✓)	No	( )	
Auto. Wash. Machine	Yes	(✓)	No	( )	
Site Suitable	Yes	(✓)	No	( )	

Character & Porosity of Soil clay
Percolation Rate .49pd 1/ft²
Topography 60%
Depth to Water Table 4'+
Rock or other impervious formations none

Lot Area existing

✓ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System — NOT TO SCALE

New tank

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900+ Linear Ft. 300+
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Mike P. Leazar

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY A.C.P. and D.R.H.

COMMENTS: Tank was replaced to 1250 gal because old tank ~~had~~ had no baffle wall. owner

CERTIFICATE OF COMPLETION BY Andre C. Pierce, R.S. DATE 6/5/89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR James Doug Brown DATE 6/2/89 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 150W T.L 1180 (Doolie Rd.) TR Whipporwill ~ 1/4 mile on left S. R. No. _____

SUBDIVISION NAME C L and T LOT NO. 19 SECTION OR BLOCK NO. 10

House (✓) Mobile Home ( ) Business ( ) Other Replacing mobile home with home


No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit	Yes	(✓)	No	( )
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	( )	No	( )

Character & Porosity of Soil existing system
Percolation Rate _____
Topography _____
Depth to Water Table _____
Rock or other impervious formations _____

Lot Area _____

_____ Basement with Plumbing Lake Basement without Plumbing _____ No Basement



Plot of System

Size of Tank existing Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: James Doug Brown

IMPROVEMENTS PERMIT BY Andrew C Griffin

COMMENTS: lake level is down 2.3'. Stay 50' back from high water mark.

3rd line is being added because old drainfield is not worth using. This is determined after uncovering system.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

my copies