
THIS IS TO CERTIFY THAT ON THE 31 DAY OF March 19 89 I, SURVEYED THE PROPERTY SHOWN ON THIS PLAT, AND THAT THE TITLE LINES AND THE WALLS OF THE BUILDINGS IF ANY ARE SHOWN HEREON.

SIGNED _____
REGISTERED SURVEYOR



LAKE NORMAN

N. 18-21 W. 105.64

N. 30-04 W. 109.14

SEE INSERT

82.6 Wood Deck

20.6 2 Story Frame Comp. Ref. No. 1

16.6

13.7

8.3

21.3 Frame Bldg.

15.2

S. 38-18 W. 227.98

Power Pole

116.6

Gravel Drive

3

0.67 AC.

N. 65-03 E. 187.09

2

4

Old Iron

S. 38-18 W. 6.40

N. 51-42 W. 6.37

S. 38-18 W. 11.20

3.3

Well House

2.0

S. 51-42 E. 6.37

S. 38-18 W. 155.38

2

3

R/W

Power Pole

Power

S.R. 1253

60

L = 204.82

L = 200

55.00

87.31

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Thomas Gregory APPLICATION DATE _____

ADDRESS: _____

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 11/13/02

LOCATION OF SITE: Cla. T#3 Sec 10 PROPERTY SIZE: _____

WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____

EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	Brn SCL GR FR						PS .3
		6-24"	Rd Brn CL						
		24"-48"	Rd Brn C						
			w/Few Mica Flakes	SAP Inclus & Common					
2									
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____

COMMENTS: _____