4637610322

13417

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Margaret C Harwell DATE 10/31/91 PERMIT NO. 2K-A-63

PHONE: Business _____ Home 873-1305

LOCATION Oak Tree Rd, Brawley School TR on Oak Tree 2 mile on (L) before road

S. R. No. _____


SUBDIVISION NAME _____ LOT NO. 63 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms	2	No. Bathrooms	1		
Garbage Disposal Unit	Yes ( )	No (✓)		Character & Porosity of Soil	P-C
Auto. Dishwasher	Yes (✓)	No ( )		Percolation Rate	4
Auto. Wash. Machine	Yes (✓)	No ( )		Topography	Some
Site Suitable	Yes (✓)	No ( )		Depth to Water Table	>48"
				Rock or other impervious formations	None observed

Lot Area 30,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3 @ 75' x 3'

Sq. Ft. 675 Linear Ft. 225

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by JC Backhoe Service

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: D-Box with speed levelers

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 10/31/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold