DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET____OF_____
PROPERTY I.D.#:_____
PROPERTY RECORDED:_____
COUNTY:_____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Barry Jenkins OWNER:__AGENT:__ PHONE:_____
ADDRESS:_____ APPLICATION DATE:_____ DATE EVALUATED: 12-6-96
_____ PROPOSED FACILITY:_____
_____ PROPERTY SIZE:_____
LOCATION OF SITE: lot 33 Dorie Meadows
WATER SUPPLY: On-Site Well____Comm. Well___Public___Other_____ EVAL. METHOD: Auger Boring___Pit___Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	L 10-15%	0-7	gr brn sil	fr					PS .3
		7-39	sandy clay loam	fr ss sp		numerous manganese stains			
		39-42+	sandy brn R	cl fr ss sp					
			many mica flakes						
2	Pasture Landscape Position Crest Toe slope Back slope Bottom Terrace Flood plain Swamp	0-8	gr brn sil	fr	36"+				PS .3
		8-36	sandy R C	fr ss sp					
		36-48+	mottled gr cl	fi sp ss sp					
			water coming in pit						
3	L 8%	0-4	l sandy brn cl						PS .3
		4-16	sandy brn R C	fr ss sp					
		16-45+	mottled gr brn cl						
			numerous y-brn mottles, mi ss sp						
4	L 6-10%	0-7	gr brn sil						PS .3+
		7-21	sandy brn R C	fr ss sp ss p					
		21-46+	mottled brn cl	fi ss sp ss p					
			micaceous, few mi ss p						
5									

AVAILABLE SPACE (.1945)_____ SITE CLASSIFICATION (.1948):_____ SITE LONG-TERM ACCEPTANCE RATE:_____
EVALUATED BY:_____ OTHER(S) PRESENT:_____
COMMENTS:_____