DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET____OF_____
PROPERTY I.D.#:_____
PROPERTY RECORDED:_____
COUNTY:_____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Jerry Jordan OWNER:__AGENT:__ PHONE:_____
ADDRESS:_____APPLICATION DATE:_____DATE EVALUATED: 12-6-96
_____PROPOSED FACILITY:_____
_____PROPERTY SIZE:_____
LOCATION OF SITE: Lot 35 Dunlin Woods
WATER SUPPLY: On-Site Well____Comm. Well___Public___Other_____EVAL. METHOD: Auger Boring___Pit___Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	V 5%	0-7	g-sl sa br sl	fr					R .3
		7-20	SSab rc	fr sp sso					
		20-48	m-wk sab yr cl	fr sp-sso sso					
			many y/gy/br/ki mottles						
2	R 4%	0-17	SSAB brn, rc	fr sp sso					R .34
		17-48	m-wk sab rc cl	fr sp sso					
3	S 4%	0-24	SSAB rbrn c	fr sp					P5 .3
		24-46	m-wk sab rbrn, brn rc cL	fr sp-sso					
			w/sc and gravelly rock on one end of pit						
4									
5									

AVAILABLE SPACE (.1945)_____SITE CLASSIFICATION (.1948):_____SITE LONG-TERM ACCEPTANCE RATE:_____

EVALUATED BY:_____OTHER(S) PRESENT:_____

COMMENTS:_____