12498

IREDELL COUNTY HEALTH DEPARTMENT

4637-90-6297

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jack West DATE 7/16/91 PERMIT NO 2K-J9-A-4

PHONE: Business _____ Home 664-6386

LOCATION Farmstead Lot 4, Brawley School Rd, TL into Farmstead, 4th lot on (L)

S. R. No. 1100

SUBDIVISION NAME Farmstead LOT NO. 4 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	(✓)	No	( )	Character & Porosity of Soil P clay
Auto. Dishwasher	Yes	(✓)	No	( )	Percolation Rate .35
Auto. Wash. Machine	Yes	(✓)	No	( )	Topography 20%
Site Suitable	Yes	(✓)	No	( )	Depth to Water Table >4'
					Rock or other impervious formations none found

Lot Area _____

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3 (2) 90'x3'
Sq. Ft. 1080 Linear Ft. 360
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by FJ Erwin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wesley Sparks RS DATE 7/16/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold