DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7-25-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 2 Kokanee Woods PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	10-2-98	0-3	brn sdl	fr					.175 LPP
		3-25/30	SABRCsdl	fr sp					
		25/30-49	massive rbrn sdl/LSap	fr sssp					
		49-62	massive sdl/LSap	fr sssp, 1948 B					
			LPP soil depth — Leaket deeper Saprolite to 60+						
2	10-2-98	0-12	sl br sc	VFSP					
		12-20	mod mot sdl rbrn sdl/massive sdl/sap/fr sap						
		20-50	massive sdl/sap		variable/wavy boundary				
		50-60	massive sdl/sap	fr-fi sssp	— .1948 possibly present?				
			leak to 60"						
3		0-18	SABRCsdl	fi sp					DS .3 @ 55"
		18-33	wk sab yrbr fr sssp		transitional sap				
		33-No	wk sab massive yrbr sdl		transitional sap				
4	10-2-98	0-2	brn sdl			4			④
		2-22	sab yrbr sdl	fr sssp					
		22-62	massive rbrn sdl/sap						
			salting loamier w/depth but still ribbons 1" @ 55"						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____