PROPERTY ID #: _____
COUNTY: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____ DATE EVALUATED: 9-26-96
ADDRESS: _____ APPLICATION DATE: _____ PROPERTY SIZE: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY RECORDED: _____
LOCATION OF SITE: Lot 9 Robinson Woods
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	loam/brwsl						RS .3
		4-18	sbk rd/l fr sp						
		18-52	wk/sbk mod/l vel fr sp sl st/p						
			few vf tub 42 z 45"						
2		0-32	sgr rd/l few vf/f/m tub fr sp SS/p						RS .35 .33 .28 .24
		32-60	wk sbk/pr-massive grd/l few vf tub ss/p						
3		0-32	sgr rd/l few ess						RS .3 .35 .33
		32-60	wk sbk/sgr rd/l few vf/f/m tub fr/l st/p						
4		0-5	brn sol						RS .025-.3
		5-28	sbk/sgr rd/l few vf/f/m tub fr/l ss/p						
		28-59	wk sbk mass rd/l few vf/f/m tub fr/l ss/p						
			few vf/f/m tub 42 z 45"						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____