ON-SITE WASTEWATER SECTION

PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____
ADDRESS: _____ APPLICANT: _____
PROPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 7-26-2
LOCATION OF SITE: lotto Robeson Lumberton PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1		0-6	gr fsl sol						
		6-31	SBK rbrn scl fr-fi sssp sssp						
		31-51	wk-mod mxd rbrn scl fr-fi sssp						
2		0-7	wk sbk rbrn scl fr						
		7-55	sbk rbrn scl fr-fi sssp sssp - few-common manganese concr) fri wk sp						
3		0-7	wk sbk brn scl						
		7-33	SBK RC fi sssp						
		33-49	wk-mod mxd rbrn scl fi sssp few mn sssp						
4		0-9	SBK RC/scl fr-fi sssp sssp						
		9-40	wk sbk yr rbrn scl/sl fr sssp						
		40-48	wk-mod yr sbk scl/sl w/common fri sssp fr sssp						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____