IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Laura Ferguson DATE 11-13-86 PERMIT NO. 599

PHONE: Business _____ Home _____

LOCATION 1303 N. SR 1300 (Fern Hill) near end – across from Broadview Loop 1254 Fern Hill S. R. No. _____

SUBDIVISION NAME L.N. LOT NO. 1002 SECTION OR BLOCK NO. 15

Future Temporary

House (✓) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil clay
Percolation Rate 4
Topography 15-25%
Depth to Water Table 4ft
Rock or other impervious formations none obs.

Lot Area 20000 sq ft – Lake


(✓) Basement with Plumbing ( ) Basement without Plumbing ( ) No Basement

1000 gal pump tank

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )



Plot of System

Installed by H. Ferguson

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DKH

COMMENTS: Electrical hook-up for pump and alarm to be checked by County Building Inspectors. System dosed at 2' Head

CERTIFICATE OF COMPLETION BY D K Hanson, RS DATE 11-13-86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

It is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold