DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: 23348
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Sada, Barbara APPLICANT: Linda Summerville
ADDRESS: 6 Croydon Ct, Pix Hills NY APPLICATION DATE: _____ DATE EVALUATED: 4/8/96
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 150 – Robinson Rd on Rt 619 PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-12	SL ~~AS~~ ~~AP~~	FR		36"			PS .3
		~~12~~-36	C SP	FI					
		36-48	C VS, VP	FI					
2		0-8	SL ~~AS~~, ~~AP~~	FR		36"			PS .3
		8-36	C S, P	FI					
		36-48	C VS, VP	FI					
3		0-12	SL NS, NP	FR		36"			PS .3
		~~12~~-36	C S, P	FI					
		36-48	C VS, VP	FI					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	1200	1200
System Type(s)	Gravity Chambered	Gravity Chambered
Site LTAR	.3	.3

OTHER FACTORS (.1946): 24" French Bottom
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Brady Freeman
OTHER(S) PRESENT: Linda Summerville, Theron Brooks