4638193334

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Chedepa Inc. DATE July 7, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1303 N TL 1300 (Fern Hill) TR Bridlewood (~2½ miles) ON R. S. R. No. _____

SUBDIVISION NAME ~~CL+T~~ LOT NO. _____ SECTION OR BLOCK NO. _____

FUTURE Temp.

House (✓) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2-3

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) ~~No~~ ( )

Character & Porosity of Soil Sandy clay
Percolation Rate ~4
Topography 15-25%
Depth to Water Table 4'+
Rock or other impervious formations Sap. trans. 24"+

Lot Area _____

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Denver Plumbing Co.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Repair Area. 1st ditch is deep. Well

CERTIFICATE OF COMPLETION BY André C. Pinn DATE 7/7/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

08817

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Chedepa Chue. DATE June 24, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1303 N. TL 1300 (Fern Hill Rd.) TR Bridlewood (.2 miles) on Rt.

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____ S. R. No. _____

Future Temporary

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2-3

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site ~~Suitable~~ PS	Yes (✓)	No ( )

Lot Area n/occ

Character & Porosity of Soil sandy clay


Percolation Rate ~1.4

Topography 15-25%

Depth to Water Table 4'+

Rock or other impervious formations saprolyte trans. 24"+

(✓) Basement with Plumbing ( ) Basement without Plumbing ( ) No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Kim Lenoch

IMPROVEMENTS PERMIT BY _____, RS.

COMMENTS: Install drainfield on contour and at a depth of 30" MAX to bottom of ditch (12"-18" cover over stone). Use drop boxes to distribute effluent.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS. DATE _____

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold