IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: J.W. Brown

DATE REQUESTED: 5-28-80

ADDRESS:

PLAT NO.:

COUNTY: Iredell

LOT SIZE: ~ 3/4 Acre

LOCATION OF SITE: 150W IR 1396 go 1.5 mile at end of road on left at culde Sac

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 15-20%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) Clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	(S) PS Sub Angular Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS 48" U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) PS None observed U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S (PS) No mottles U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	(S) PS 80 mpi U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S (PS) None U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	PS			
SOIL SERIES	Cecil			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: follow contours of hillside

Described By: Fred Cleaver

Title: S-II

Date: 5-28-80

DHS Form 2601 (2/77)
Sanitation