4638315801

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John Martin DATE 6-24-80 PERMIT NO. 181

PHONE: Business ( ) Home

LOCATION 150W TR 1396, 1st dirt street to R TR at end TR on dirt street 1/ast lot on left S. R. No.

SUBDIVISION NAME Swiney property LOT NO. 6 SECTION OR BLOCK NO.


House ( ) Mobile Home (X) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (X)
Auto. Dishwasher Yes ( ) No (X)
Auto. Wash. Machine Yes (X) No ( )
Site Suitable Yes (X) No ( )
Lot Area 1 acre

Character & Porosity of Soil Clay loam - PARENT material
Percolation Rate 50 min/in - 100 min/in
Topography 2-10%
Depth to Water Table Unknown
Rock or other impervious formations NONE observed

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 750 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual (X)
Public ( )

Installed by Wayne Orbison

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY David R Hinson

COMMENTS: At tank + 1st 20' LINE, Cegil clay - Rest of LINE in parent Material (weathered)

CERTIFICATE OF COMPLETION BY Ted Clemmons DATE 6-24-80

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold