ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION

OWNER: Dennis Hallman APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8/8/2001

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: _____ PROPERTY RECORDED: _____

WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

SE = Slightly Expan

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-13"	Rd/Brn C m SBK	SS, SP, SE	Fi-FR				PS .3+
		13-48"	Rd/Brn C m wSBK	SS, SP, SE	FR w/few				
			Sdl/Brn SAP	Indus. & Some Mica					
2		0-16"	Rd/Brn C m SBK	SS, SP, SE	FI-FR				B .3+
		16"-48"	Rd/Brn C m wSBK	SS, SP, SE	FR w/few				
			SAP Indus & Some	Mica					
		0-14"	Rd/Brn C m SBK	SS, SP, SE	FR				PS .3
		14-48"	Rd/Brn C m wSBK	SS, SP, SE	FR				
			Common Mica &	Some SAP Indus					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Type (.1945)	PS	PS
	III	III
	.3	.3

OTHER FACTORS (.1946): None

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: M. Dotson

OTHER(S) PRESENT: _____