DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

APPLICANT
OWNER: GLENN BABLOCK — APPLICATION DATE: 122375
ADDRESS: 11305 SUNSHINE RIVER BLVD RIVERVIEW FL 33569 — 4638 53-9702
PROPOSED FACILITY: HOUSE 4BR — PROPOSED DESIGN FLOW (.1949): 450 — DATE EVALUATED: ____
LOCATION OF SITE: LOT 51 — PROPERTY SIZE: 1.25
PROPERTY RECORDED: YES
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	4/0 L	0-6	sd wk gr	fr nsp nsp	sap interfering ≥ 50%				PS .3
		6-31"	l med sbk	fr sp ss/p					
		31-48"	l med sbk	fr sp ss/p					
2	4/0 L	0-6"	sd wk gr	fr nsp nsp	sap interfering ≥ 50%				PS .3
		6-28	l med sbk	fr sp ss/p					
		28-48"	sic/sicl wk gr	fr ss sp ss/p					
3	4/0 L	SAME AS HOLE 1							PS .3
4		0-3	Rd/Brn SL						PS .3
		3-24	Rd CL m-w SBK	SS, SP, SE, FR-FI					
		24-48	Rd CL w SBK	SS, SP, SE, FR w/ few SAP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	YES	N/A
System Type(s)	LPSAS/1200	SAME
Site LTAR	.3	.3

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): SC
EVALUATED BY: L. LOOK
OTHER(S) PRESENT: M. BOWER

COMMENTS: ____