DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION

Richard Haustman 3/19/2003

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #2 Haustman - 133 Folk Home PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Below house	0-6"	Brw SCL GR to WSBK	SS, SP, SE, FR					U
		6"-22"	Yel/Brw C m-w SBK	S-SS, SP, SE FR					
		22-27	SAP w/ weathered Rock mix						
		27"	Hard rock (auger through)						
2	Beside house (left side)	0-15"	Brn C/CL w SBK						U
		15"	SAP & W. Rock mix						
3	Below house	0-12"	Brw SCL	GR FR					U
		12"-24"	Brw C	m SBK	SS, SP, SE	F-FR w/ Common Mica Flakes			
		24"	SAP - Weed	Backhoe pits					
4	AH ~20' off left sideline	0-48"	Rd/Brw	C/CL m-w SBK w/ Few SAP Inclds	SS, SP, SE	F-FR			PS .3+

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
FOR ON-SITE WASTEWATER SYSTEM

OWNER: Don Markofski APPLICANT:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 3/20/20
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE: 1
LOCATION OF SITE: Folkstone PROPERTY RECORDED:
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-18	Brw SCL						U
		18-60	SL/L SAP	Hard w/ many Rock Inclus & Some Exp. Clay					LTAR 18"
				Probably Chroma 2					
2	Pit 2	0-6	Brw SCL						PS .15 2 to 36" .3 @ 42-55"
		6-36	Brw C,S,P,SS	F					
		36-42	Quartz Rock rem						
		42-55	SL/L SAP					.3 @ 42-55"	
3	Pit 3	0-6	Brw SCL						PS .2 to 32" .3 @ 32-36"
		6-32	Brw C,S-SS, SP,SE	FI-FR w/Common Mica Flakes				Mica Flakes	
		32-60	SL SAP w/SBK to massive w/common Mica Flakes Some Quartz Rock	32"-36"					
4	36"	Trench Bottom							60"

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:

OWNER: Don Marcefski APPLICANT:

ADDRESS: APPLICATION DATE: DATE EVALUATED: 3/25/05

PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:

LOCATION OF SITE: Haustman Lot 2 PROPERTY RECORDED:

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Pit A	0-5"	Fill						
		5"-24	C Brw						
		24-48+	L SAP	w/Cl Inclus					
2	Pit B	0-6"	Fill						
		6-24	Brw C						
		24-46	L SAP	w/ Cl Inclus					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):

SITE CLASSIFICATION (.1948):

EVALUATED BY:

OTHER(S) PRESENT: