DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 2
PROPERTY I.D.#:
PROPERTY RECORDED:
COUNTY:

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Wm Michelle Freeman OWNER: AGENT: PHONE:
ADDRESS: 6399 Transit Rd. APPLICATION DATE: DATE EVALUATED: 4/30/02
E Amherst, NY. 14051 PROPOSED FACILITY: 3BD House
PROPERTY SIZE:
LOCATION OF SITE: Haustman - Lot 3 Corner of Collingwood + Folkstone on (L)
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring Pit Cut ✓

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	LS (LOW)	0-4	BR SCR GR	FR SS SP					
		4-16	ABK - C	FI S P					.25
		16-35	SBK - CL	FR SS SP				RELIC	
		36-49	> 50% Rock						
2	T MID.	0-27	AB C	FI S P SAP					
		28-54	M SBK SL SAP.	FR SS SP					.3
3	T (M)	0-4	BR SCR	GR FR SS P					
		4-24	ABK - 4 RC	FI S P					.1 LPP
		25-44	CL SAP w/ Rock	FR S P					
(4)	T LOW	0-18	SBK C	FI S P					
		18-48	M SBK CL	FR SS P.				W. ROCK INCL.	PAWZ .3 ACCPTD
5									

AVAILABLE SPACE (.1945) SITE CLASSIFICATION (.1948): SITE LONG-TERM ACCEPTANCE RATE:
EVALUATED BY: OTHER(S) PRESENT: B Freeman
COMMENTS:

DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Wm. Dreamm OWNER: AGENT: PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: ____
PROPOSED FACILITY: ____
PROPERTY SIZE: ____
LOCATION OF SITE: Haunstmen - Lot 3
WATER SUPPLY: On-Site Well ____ Comm. Well ____ Public ____ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ____ Cut ____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
LS 1		0-10	SBK - Sndl			37" yR SAP		yR-SAP Rock	.3
		11-	MICA VK - c - cl	SEXP 1:1 SS - SP					
		24	MICA VK SBK - cl	SEXP 1:1 - SS - SP					
		39-49	MICA SBK - cl	SEXP 1:1 SS - NP					
TERRACE RSB E		0-6	CH3 SBK -SCl SAP.	SEXP 2:1 SS -	CH3 15-18 M 7 OFF COLOR	4 INCH C			
		6-18	VK SC SAP	S - SP					
		38	S SAP						
3									
4									
5									

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: ____
EVALUATED BY: ____ OTHER(S) PRESENT: ____
COMMENTS: ____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Wm. Dream APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 11/7/03
PROPOSED FACILITY: 480/House PROPOSED DESIGN FLOW (.1949): 480 PROPERTY SIZE: ~2 AC
LOCATION OF SITE: Haustman Lot 3 PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	T FS 10-nose IRR. Road Right of Way	0-4	Br. scR / GR.	FR SS SP	Red	u	u		
		5-19	ABK / 4R SAP-C	EXP. FI S-P					
		20+	Rock						
2									
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): Shallow Rock
SITE CLASSIFICATION (.1948): u

EVALUATED BY: Sparks
OTHER(S) PRESENT: John Mundelly

COMMENTS: _____