DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Bradley Cust. Homes APPLICANT:
ADDRESS: 224 Collinswood APPLICATION DATE: DATE EVALUATED: 1/4/10
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: C.a.T Sec 14 Lot 65 PROPERTY RECORDED:
WATER SUPPLY: ☒ Private ☒ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

* SE = Slightly Saprolite

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTA
1	LL 6%	0-6	Brw SCL	GR FR	—	48"	—	—	PS .3
		6-28	Rd/Brw C m	SBK SS,SP,SE FR					
		28-48	Rd/Brw C m w	SBK SS,SP,SE FR					
2	LL 6%	0-4	Brw SCL	GR FR	—	48"	—	—	PS .3
		4-24	Rd/Brw Cm	SBK SS,SP,SE FR					
		24-48	Rd/Brw CL w	SBK SS,SP,SE FR					
3	LL 4%	0-4"	Brw SCL	GR FR	—	42"	42" LSAP	—	PS .3+
		4-18"	R C m	SBK SS,SP,SE,FR					
		18-42"	Rd/Brw CL w	SBK SS,SP,SE,FR					
		42-48"	LSAP SS-WS	SP,SE-WE, FR	—				
4	LL 4%	0-4"	Brw SCL		— though				PS .3 to 42"
		4-42"	Rd/Brw C/a						
		42"	Hit Rock & Couldn't auger						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Pump Panel Blk	LP Panel Blk
Site LTAR	.3	.3

OTHER FACTORS (.1946): None
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Maria Dotson
OTHER(S) PRESENT: Wayne & Rusty Orbison Jim Bradley