DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jerry Cheney APPLICATION DATE 1/7/2003
ADDRESS: 230 Collingswood Rd. DATE EVALUATED: 1/14/03
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 360GPD PROPERTY SIZE: ___
LOCATION OF SITE: Collingswood Rd. PROPERTY RECORDED: ___
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other EXISTING
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LS 4-5% uniform	0-8	sbk / l	Fi SS SP	PS				
		9-25	wk sbk / mic cl	FR SS SP	PS				
		26-34	Fi sbk / cl SAP	FR SS SP					
		35-48	fi gr / l SAP	FR SS NP	PS				.3-.35
2	LS 4%	0-13	GR→sbk / l	Fi SS SP					
		14-28	sbk / cl mic	FR SS SP					
		29-36	fi sbk / cl SAP	FR SS SP					
		37-48	Fi gr / l SAP	VFR SS NP					.3
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	
System Type(s)	25%	50%
Site LTAR	.3	.3

OTHER FACTORS (.1946): existing well (block bldg.)
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Sparks
OTHER(S) PRESENT: Cheney

COMMENTS: ___