DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 11-20-97
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 19 Hardscrew Sect 9 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Move house back to front of lot — pump to front of lot

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 2-3%	0-26	sl/l, 0 c/cl	[illegible] ss/sp/sap		(4)			
		26-48	wk sbk RDN cl/sap	sl sticky/plastic					
2	L 20-25%	0-20	sgr c cl/cl	fri ss/sp/sap		(4)			
		20-32	fm sbk with some hardware mn/gravel cont.						
		32-46	wk/sap						
3	L 2-3%	0-32	mm sbk/gr x cl	fri ss/sp/sap - few hardpan					PS .03 @ 32"
		32-42	wk sbk rdn cl/sap	hardpan fri ss/sp/sap					
4	L 2-3%	0-36	gr/sbk cl/cl	fri ss/sp/sap					PS .03+
			[illegible] mm/f sap						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

Landscape position worsens being slightly concave from middle of lot towards rear
Soil [illegible] as you proceed towards rear