1/ SITE WASTEWATER SECTION

COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Dan Winbish APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8297

PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360gpd PROPERTY SIZE: _____

LOCATION OF SITE: Lot 2 D Winbish PROPERTY RECORDED: _____

WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (1941) 1942 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR | 1943 SOIL DEPTH | 1950 SAPRO CLASS | 1944 RESTR. HORIZ. | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | L ~5-10% | 0-40 | SiL gr rc/cl | fr sp ssp | | | | | PS .3 |
| | | 40-48 | mSbk rcl | fr sspsep | | | | | |
| 2 | L 6-8% | 0-11 | gr - lsm sil | fr | | | | | PS .3 |
| | | 11-37 | SiL rc/mcl | fi sp ssp | | | | | |
| | | 37-48 | msbk rcl | fr sspsep | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____