DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Penny Fisher APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 2-26-96
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 420 gpd PROPERTY SIZE: .71 ac
LOCATION OF SITE: Lot 6, Harbor view PROPERTY RECORDED: NO
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	R-S 2%	0-2	Brn scl	fr					.3
		2-13	sab rc	1:1 fr, sp					
		13-36	MSsab rcl	1:1 fr					
		36-48	M-wksab g-r cl	1:1 fr-fi					
			Sc mix of Saprock						
2	R-S 2%	0-4	Brn scl	fr					.3
		4-16	sab rc	1:1 fr, sp					
		16-26	MSsab rcl	1:1 fr					
		26-48	m-wksab g-r scl/cl	1:1 fr					
			w/ mix of Saprock						
3	S 2-4%	0-4	R brn cl	fr					.3
		4-19	sab rc	1:1 fr, sp					
		19-26	MSsab R brn/ltgr cl/c	1:1 fr-fe	SAP-SP				
		26-48	m-wksab R cl	1:1 fr					
			few yellowish mottles						
4	L 6%	0-21	sab brn cl	1:1 fr					.3
		21-37	SSab rc	1:1 fr, sp					
		37-48	m-wksab R cl	1:1 fr-fe					
			few mot of Saprock						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

P1 #6 L 0-21 Brn SAB 21-36 SAB 36-48 m-SAB fr
P1 #4 L 0-39 Brn SAB RC few sc quartz 39-40 SAPROCK fr .354