DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Stumpy Creek LLC APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6/12/19
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot #33 Harborview V PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1		0-30"	R A/L SmSBK	SS,SP,SE,F-FR	w/some Yel/Brw		SAP incl.		PS .3
		30"-48"	R CL mFSBK	SS,SP,SE FR	w/some Yel/Brw		SAP incl.		
2		0-24"	R A/L SmSBK	SS,SP,SE F-FR					PS .3
		24"	Quartz Vein						
		24"-46"	R A/L mFSBK	SS,SP,SE	F-FR w/some	Yel/Brw	SAP incl.		
		46"-LR	R CL SAP						
3		0-30"	R A/L SmSBK	SS,SP,SE F-FR					PS .3
		30"-LR	R CL mFSBK	SS,SP,SE	FR w/some Yel/Brw incl.		SAP		
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
R		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____