DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Danny Fisher — APPLICANT: ___
ADDRESS: ___ — APPLICATION DATE: ___ — DATE EVALUATED: 2-26-96
PROPOSED FACILITY: SFR — PROPOSED DESIGN FLOW (.1949): 480 gpd — PROPERTY SIZE: 1.5 Ac
LOCATION OF SITE: Lot 8 Lakeview Est Stanfield NC — PROPERTY RECORDED: NO
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed — Look @ Dentyard

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1 Pit	LSS 8% Footslope MS	0-4	brn cL	fr					-3
		4-15	sab rc	1:1 fi sp					
		15-20	msab rcl	1:1 fr ss sp					
		20-48	wksab r-y 02/2	1:1 fr ss sp					
2 Pit	SS LSS 4-6%	0-6	brn cL	fr					-3
		6-33	sab rc	1:1 fi sp					
		33-48	M-wksab y-r cL	1:1 fr					
			few red yellow						
3 Pit	MS 15%	0-3	brn cL	fr			11"+		
		3-11	sab r many cod	fr					
		11-23	gr. SL sap	fr					
		23-48	wksab L sap	fr					
4 Pit	ELEVATED 2	0-9	brn cL	fr					-3
		9-22	sab rc	1:1 fi sp					
		22-48+	mwksab rcL	1:1 fi-fr ss sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

P-15 0-8 brn subsoil 8-16 sap 16-48+ wksab 1:1 wk sap — 3-27-96 AK #2 0-30 subsoil 30-40 wksab