ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Stumpy Creek LLC APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 1-20-98

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Seat & Harborview Lot 14 PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1		0-13	SAB rc/cl	fr sp sss ps exp					PS .3
2		0-12	SAB rbrn c/cl fr fi sp SExp few mtles water in pit bottom eliminate old burn						PS .3
3		0-16	SAB rbrn c/cl ~6" water in bottom of pit due to landscape position - upslope side of old farm burn much rainfall over last week		modify by ditching along eliminate old farm burn				PS .3
4		0-16	wk SAB brn, rbrn cl fr sp-sss ps exp						PS .3
		16-13	SAB brn R c/cl fi sp SExp						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____