DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jenny Fisher APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 2-26-96
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 480 gpd PROPERTY SIZE: _____
LOCATION OF SITE: Lot 4 Harborview Sub of Stumpy Creek PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LSS 2-4%	0-7	msab Rkwcl	1:1 fr					.3+
		7-26	sab rc	1:1 fr, sp					
		26-48	m-vfsab rcl	1:1 fr					
2	LSS 2-4%	0-6	gr. bkwscl	fr					.3+
		6-23	sab rc	1:1 fr, sp					
		23-48	mvfsab rcl	1:1 fr-fi					
3	LSS 2-4%	0-5	msab k-bkwcl	1:1 fr					.3+
		5-16	sab rc	1:1 fi, sp					
		16-48	m-vfsab rcl	1:1 fr, sp					
			common gritic matter						
			few soft rock fragments						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____