08637

IREDELL COUNTY HEALTH DEPARTMENT 4638829131

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Rodney Lot Lakewood DATE April 7, 88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 150 W. SR 1303 (Peeler Rd.) TR Wilson Lake Rd. 1/2 mile on left S. R. No. _____

SUBDIVISION NAME CLT Lake Norman LOT NO. 19 SECTION OR BLOCK NO. 11


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil		
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate		
Auto. Wash. Machine	Yes (✓)	No ( )	Topography		
Site Suitable	Yes ( )	No ( )	Depth to Water Table		
			Rock or other impervious formations		

Lot Area Existing

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank Existing Gals.

Nitrification Field:
No. of Lines Existing
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines _____

Water Supply: Individual ( )
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing system showing no sign of malfunction at time of inspection.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: D R Hinson JR DATE 4-7-88

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold