DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
[illegible] COUNTY HEALTH

Sheet ___ of ___

PROPERTY ID #: [illegible]

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Penny Zahn — APPLICANT: ___

ADDRESS: ___ — APPLICATION DATE: ___ — DATE EVALUATED: ___

PROPOSED FACILITY: SFR — PROPOSED DESIGN FLOW (.1949): 480gpd — PROPERTY SIZE: 1.38ac

LOCATION OF SITE: Lot 4, Sect I, Hitchcock — PROPERTY RECORDED: no

WATER SUPPLY: ☐ Private ☒ Public ☒ Well ☐ Spring ☐ Other ___

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut — NEED new pits

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 2-4%	0-3	Sandy	fr					.3
		3-7	sasb RC	1:1 fi-fr					
		7-13	msab RCL	1:1 fi-fr					
		13-54	wksab lm-R lgt CL/L	1:1 fr					
			many y/rdsh mottles						
2	L 2-4%	0-10	wksab R many f/gr C	fr					
		10-48	m-wksab R CL						
			many m/f/vf R						
			Common y/rdsh mottles						
3	L 2-4%	0-6	sab lm-R CL	fr					.3
		6-16	sab RC	1:1 fi SP					
		16-48	m-wksab RCL	1:1 fr-fi SS SP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___

SITE CLASSIFICATION (.1948): ___

EVALUATED BY: ___

OTHER(S) PRESENT: ___