SION OF ENVIRONMENTAL HEALTH
ITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Stumpy Creek LLC APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6-2-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 57 Sect II Harbor Landing PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-31	SAB RC/VRCL	FR SP-SSP					PS .3 @ 31"
		31-48	WKSAB	MINERAL LSAP					
2		0-41	M-WKSAB/AB	RC/CL FR SP-SSP					PS .3 @ 24"
		41-51	WKSAB/AB-MASS	RC/SP / LAMINATED SILT/SP FR SSP					
3		0-31	M-WKSAB	RC/CL FR SP-SSP SAP					PS .3 @ ≤ 31"
		31-48	WKSAB	VFR L-FSL FINE SAP FR SSP					
4		0-13/36	SAB	RC/CL FR SP-SSP					(.3 with 36" SOIL)
		13/36-40	LSAP	FR SSP					
		40/43	(SL SAP Good Separable)	FR SS-NP					
			36" soil on end of pit - not much soil depth on side pit walls						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____