DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: Stumpy Creek LLC APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6-8-95
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 62 Sect 4 Arbor Landing PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-48	sab rc/cl	fr sp-ss sp ss p					PS .3
2		0-48	sab rc/cl	fr sp-ss sp ss p					PS .3
3		0-7	gr bnv sl/scl fr						PS .3
		7-50	sab rc/cl	fr ss sp					
			few q. bav mottles, few il sk/pve						
4	9-16-95	0-5	gr bnv scl	fr (sp)					PS .25-3 @ 37"
		5-22	sbk rc/cl	fr sp					
		22-37	wk sbk gycl	fr ss sp sa w					
			few il q. sk/pve						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

9-29-98
Change to cream (septic system)
per Danny's request



LOT #62
HARBOR LANDING

DAVIDSON TOWNSHIP
APRIL 05, 1998

IREDELL COUNTY, NC
SCALE: 1" = 60'