DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Jumpy Creek LLC APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 6-9-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 91 Sect 4 Harbor Landing PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

FLAG RIGHT MORE PS deeper than 37" here

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	g-sub hor scl	fr ss sp					PS @ 37"
		4-37	sbk rd cl	fr so-ss sp so	37"				
		37-58	AC mainly y c	vfi VSVD org					
			Gleying beginning w/ depth						
			few ind sap/wp						
2		0-4	g hor scl	fr					PS @ 25
		4-35	sbk rd cl	fr ss sp so					
		35-52	VFSVD rd cl	fr-fr so-ss sp					
			Mn nodules/coatings > 43"						
3		0-5	g. VFSVD hor scl	fr					PS ~25-.3
		5-26	sbk rd cl	fr so ss sp	sap				
		26-48	VFSVD rd cl	fr sp ss sp					
			Ind gwp/sap						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7-11-22
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 90 Sec 4 Harbor Landing PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS 1943 SOIL DEPTH	OTHER PROFILE FACTORS 1956 SAPRO CLASS	OTHER PROFILE FACTORS 1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	loam sdlfr						PS .3 @ 2.40
		9-48	sbk rbrk/cl	fr ss/sp					
			few med fine y-brn/mottles		(increasing w/depth)				
2		0-4	loam sdl	fr					PS .3 @ 2.36
		4-18	sbk rc	fr-fi sp					
		18-36	mbk/sbk rbk	fi ss/sp					
		36-48	rbrk/cl	fr ss/sp					
			few med prom gry/brn/red coatings						
3	9-21-22	0-12	loam sdl						PS .3 @ 2.43
		12-42	sbk rc/fri	fi ss/sp					
			few fine mica						
			Pit only 42" dep						
4	9-21-22	0-14	loam sdl						PS .25-.3
		14-40	sbk/mbk rbrk/cl	fi sp					
			few med prom gry/brn/red coatings						
			few fine mica						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____