DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-9-20
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 82 Sec 4 Harbor Landing PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	1956 SAPRO CLASS	.1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1		0-36	SAB RC/CL	fr SP-SSSP fw	mil sap/wk	sequently	surface mech		PS .3 @ < 36"
		36-40	wr/sap/soil mix						
2		0-4	dk brn sl	fr		(U)		(U)	(U)
		4-12	AB ybrn c	fi SP mod fw					
		12-30	hard wr/rock/sap/cl mix						
					mostly wr/rock				
3		0-10	SAB rbrn cl	fr SSSP		(U)		(U)	(U)
		10-34	Massive wr/soil mix						
					mostly wr				
4		0-7	gr - fine dk brn sl fr						
		7-13	SAB/SR RBRN C fi-vfi	mixed/sap SP		(U)		(U)	(U)
		13-33	Rock/wr/some soil						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

#5 0-3 dk brn sl sd/cl, 3-20 SAB R, yr-R c/cl, 20-39 massive yr cl SAP vfi (U)