ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 9-1-9
LOCATION OF SITE: Lot 11 2804 Harbor Landing PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut MORE PITS NEEDED where X
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1941 RESTR. HORIZ.	PROFILE CLASS & LTAR
1		0-7	brn scl	fr					PS .3
		7-21	SAB RC	fr sp sexp					
		21-55	wk SAB yel/L	fi-fr ss sp sexp					
			few fine ind SAP						
2		0-3	gr brn scl	fr					PS .3*
		3-16	SAB RC	fr sp					
		16-65	wk SAB RCL	fi ss sp sexp					
			hard wet/sap few fine ind SAP	wet 16-36" on sh of pit					
3		0-3	brn scl		* mostly soil - bit some rock/sap				PS .3 @ L 30°
		3-30	SAB RCL	fr sp sexp					
		30+	cL w/ gneiss rock						
4	9-25% NP	0-21	SAB RC	fr sp sexp					
		21-35	hard wet sap/ w/ some mica sand						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Stump Park LLC — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 9-23-98
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: lot #1 (continued) place of Horton Rd — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5	BS	0-9	SaBrC	(FR) SP					BS
1		9-12	wkSab gr	FI SSSP					-3
									&C 42
			ft cobbly SaBrC						
6		0-5	Rhw scl						B
2		5-25	SaBrC	FR SP					-3
		25-40	wk Sab gr scl	ft SSSP					
			few bits w/ SaBrC						
7		0-4	Rhw scl						B
3		4-32	SaBrC	(FR) SP					-25-3
		32-59	wk Sab gr scl	ft SSSP					
			and gravel SaBrC		predominately soil				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____