DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-1-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 13 Sect 4 Harbor Landing PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-12 | SaLo R C | fr ss sp | | | | | PS .3 |
| | | 12-26 | mk sa lo rock | fr ss sp | | | | | |
| | | 26-56 | wk fi sa lo gravel | fi ss sp stg | few indyw R, pale mottles | | | | |
| 2 | | 0-5 | brn sl fr | | | | | | PS .3 |
| | | 5-48 | SaLo rock | fi sp ss sp stg | | | | | |
| 3 | | 0-5 | brn sl | fr | | | | | PS .3 |
| | | 5-41 | SaLo rock | fi sp ss sp | | | | | |
| | | | few ind Rock/wR | | | | | | |
| 4 | | 0-7 | brn sl | fr | | | | | PS .3 Colluv |
| | | 7-36 | SaLo rock | fi sp ss sp | | | | | |
| | | | few ind stg | | | | | | |
| | | | Pit ends 36" loss | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____