DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET____OF_____
PROPERTY I.D.#:_____
PROPERTY RECORDED:_____
COUNTY:_____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Mike Kern OWNER:__AGENT:__ PHONE:_____
ADDRESS:_____ APPLICATION DATE:_____ DATE EVALUATED: 3/13/95
_____ PROPOSED FACILITY:_____
_____ PROPERTY SIZE:_____
LOCATION OF SITE: Lot 29 Now Lot 28 Mills Knoll Road
WATER SUPPLY: On-Site Well____Comm. Well___Public___Other_____ EVAL. METHOD: Auger Boring___Pit ✓ Cut___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1		0-5"	sa b L				PS		.35
		5-40"	sa b c						
		40"	hard scattered rock						
			in pit (prim. gravel)	micaceous					
			pit stopped @ 41" due to rock						
2		0-7	sa b - cL						.3
		7-19"	sa b - c						
		19-48"	wk sa b - cL	micaceous					
			restrictions start rock beginning @ 28"						
3 X New Pit 3/13/95		0-4	sa b - cL	fr					
		4-11	sa b - c	mfi					
		11-36	wk sa b - cL	fi					
		36-48+	vwk sa b - L w/ medium gravel	sl fi					
4									
5									

AVAILABLE SPACE (.1945)_____ SITE CLASSIFICATION (.1948):_____ SITE LONG-TERM ACCEPTANCE RATE: .5
EVALUATED BY_____ OTHER(S) PRESENT:_____
COMMENTS: Pits exhibit shallow profile overall. Keep laterals shallow