IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Norman Shoots DATE 4-23-80 PERMIT NO. 97

PHONE: Business _____ Home _____

LOCATION 150W TR 1303 TR 1300 TR 1449 BRight on 2nd dirt street BRT into drive, lot on left at point S. R. No. _____

SUBDIVISION NAME Lake Norman LOT NO. 187 SECTION OR BLOCK NO. 15


House (X) Mobile Home ( ) Business ( ) Other Repairs

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes	( )	No	(X)
Auto. Dishwasher	Yes	(X)	No	( )
Auto. Wash. Machine	Yes	(X)	No	( )
Site Suitable	Yes	(X)	No	( )

Lot Area 1.1 acres

Character & Porosity of Soil Clay loam
Percolation Rate 100 mpi
Topography 8-15%
Depth to Water Table 6
Rock or other impervious formations None Observed



Plot of System

Size of Tank Existing Gals.
Nitrification Field:
No. of Lines 1
Sq. Ft. 200 Linear Ft. 100
Depth of Stone in Lines 16
Water Supply: Individual (X)
Public ( )

Installed by Lyman Septic Tank

IMPROVEMENTS PERMIT BY Fred Clemmer + David Hinson

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Fred Clemmer DATE 4-23-80

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Norman Shorts DATE [illegible] PERMIT NO. _____

PHONE: Business _____ Home 872-2099

LOCATION 1303 TL on 1300 2nd Rd Towards Bart Church 1st Rd TR at end S. R. No. 1330

SUBDIVISION NAME Lake Norman LOT NO. 189 SECTION OR BLOCK NO. 15


House ( ) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No ( )
Auto. Dishwasher Yes ( ) No ( )
Auto. Wash. Machine Yes ( ) No ( )
Site Suitable Yes ( ) No ( )

Lot Area 1 acre

Character & Porosity of Soil Sandy clay loam
Percolation Rate 25 min/inch
Topography 20% Slope
Depth to Water Table 10'
Rock or other impervious formations None



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 688 Linear Ft. 229
Depth of Stone in Lines 24"
Water Supply: Individual ( )
Public ( )

Installed by David Tucker

→ = 688 ft² = 229 lin ft.

IMPROVEMENTS PERMIT BY T. C. Moore

COMMENTS: System placed in area below where was originally layed out due to grade. This area had better soil & than original area.

CERTIFICATE OF COMPLETION BY T. C. Moore DATE [illegible]

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold