DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Tony C Jacobs OWNER: AGENT: ✓ PHONE: ____
ADDRESS: Crescent Resources APPLICATION DATE: ____ DATE EVALUATED: 11/22/94
PO Box 1003 PROPOSED FACILITY: SFR 4BD 900 / /
Charlotte NC 28201 PROPERTY SIZE: ____
LOCATION OF SITE: Beacon Pointe lot 9
WATER SUPPLY: On-Site Well ____ Comm. Well ✓ Public ____ Other ____ EVAL. METHOD: Auger Boring ____ Pit ✓ Cut ____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS	HORIZON LTAR
1 Old pit		0-24"	gr - scl	1:1/fr					≥3
		24-36	broh - c	1:1/fr-vfi					
		stopped @ 36" due to rain water in pit							
2		0-12	gr sbk scl	1:1/vfr					≥3
		12-34	sbk c	1:1/vfi					
		34-44	wk sbk cl	1:1/fi					
		44-48	wk sbk - cl w/ sth.	1:1/fr-fm					
3									
4									
5									

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: ____

EVALUATED BY: ____ OTHER(S) PRESENT: ____

COMMENTS: Old pit partially filled w/ water @ 36" down - Heavy rain (1"+) on and 11/21/94
PRBPS soil Depth Spaces

To : JESSICA WOLFE

CURVE	DELTA ANGLE	RADIUS	ARC	TANGENT	CHORD	CHORD BEARING
C 3	6°02'35"	622.50'	65.66'	32.86'	65.63'	S 60°21'25"W

NEED A BOB REVIEW



LINE	BEARING	DISTANCE
L 1	N 08°20'24"E	15.74'
L 2	S 88°50'34"E	17.81'
L 3	N 04°53'00"W	29.35'
L 4	N 17°47'44"W	25.41'
L 5	N 33°23'02"W	39.55'
L 6	N 20°27'00"W	35.70'
L 7	N 27°21'13"W	28.24'
L 8	N 39°40'13"W	7.17'

OK RLC

DG 22