4639108721

IREDELL COUNTY HEALTH DEPARTMENT

11876

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Anthony Crosby DATE Aug 15, '90 PERMIT NO. 3C-10-A-153

PHONE: Business _____ Home _____

LOCATION 803 N. TR 1300 (Fern Hill) past 1449 (Riverbend) ~0.1 mile TR Harvest Lane (Gravel Rd.) ~500' on left S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site ~~Suitable~~ PS	Yes (✓)	No ( )	

Character & Porosity of Soil clay loam.
Percolation Rate 2.3
Topography 2% 44
Depth to Water Table _____
Rock or other impervious formations none obs.

Lot Area ~3/4 Ac.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 810 Linear Ft. 270
Depth of Stone in Lines 12"
Water Supply: Individual (✓) well at, Public ( ) parents house

Installed by James Hudler

I understand and agree to install septic tank system as specified on this Improvements Permit.

LAICE

Signed: _____

IMPROVEMENTS PERMIT BY DCH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY David R. Hanson, EHS. DATE 8-15-90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold