DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI
ADDRESS: _____
APPLICANT: _____
APPLICATION DATE: _____
DATE EVALUATED: 6-5-96
PROPOSED FACILITY: SFR
PROPOSED DESIGN FLOW (.1949): 360 gpd
PROPERTY SIZE: _____
LOCATION OF SITE: Lot 953
PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L ~30%	0-24	gr brn sL	fr					=3
		24-35	gr-wk subbl brn sL	fr					
		35-48	SLSAP	fi-fr					
2	L 20-30%	0-17	gr brn sL	fr					
		17-42	R-brn sap	fi					
3	upper side	0-36	gr brn sL	fr					=3+
		36-60	gr sLsap	fi					
	lower side	0-30	gr brn sL	fr-vfr					=3+
		30-48	LS sap	fi-fr					
4		0-24	gr brn sL						=3+
		24-42	gr brn sLsap	fr					
		42-60	gr brn sLsap	fi					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

P#5 0-36 gr brn sL
36-60 gr brn sLsap - fi =3

P#6 0-11 gr brn sL
11-30 Sab gr brn sL
30-43+ brn SAP vfr =3+