DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 10-16-03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 3 Beacon Pt. PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1			RdCL	bandsbr/ybrn & chr 2 dissecting pat RdCL underneath on N end possibility of additional testing	17"+				(U)
2		0-5 5-48+	gr brn scl fri ssp wk fsbk RdCL fri ssp common ybrn mottles		28"				1 LAP
3		0-40"	gray scl		6"+				(U)
4		0-22	brn-gr scl fri ssp		10"+				(U)

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): U
EVALUATED BY: [illegible]
OTHER(S) PRESENT: Paul Pennington

COMMENTS: _____

#5 0-6 brn scl fri ssp
6-24 wk fsbk brn/ybrn scl fri ssp 24"+ chr 2 (U)
24-60 wk fsbk mottled scl fri

#6 0-5 gr brn scl fri ssp
5-50 wk fsbk brn scl fri ssp
chr 2 27"+ (U)

28"+ V

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: Beacon Partners
ADDRESS: ___ APPLICATION DATE ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 460gpd DATE EVALUATED: 11-7-03
LOCATION OF SITE: 3A SFE the 3 Beacon Pl lots PROPERTY SIZE: ___
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-22	gr fsl/lsk sns sl	fr sss p					.3
		22-44	m fsbk/lsk RC	fr sp sep					
		44-49	w k fsbk yel	fr sss p	Restrictive hor				
2		0-19	gr. w k sgr sns sl/fsbk	fr sss p			PS 49"+		.3
		19-38	m-s fsbk RC	fr sp sep					
		38-49	w k fsbk RC	fr sss p					
		49-55	L/PSLSAP	fr sss p	Restrictive hor				
3	15-20% V	0-13	w k sgr RM sol	fr sap					.3
		13-29	m fsbk/lsk RC	fr sp sep					
		29-47 (BC)	m fsbk yel	fr sss p	Restrictive hor				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Pm 25% Red	Pm 25% Red
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: DM
OTHER(S) PRESENT: Pool Manager

COMMENTS: ___