4639378049

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Richard Lee Lyerly DATE 8/31/88 PERMIT NO. 17-B

PHONE: Business 2067 Home

LOCATION 1303 N. TL (Fern Hill) TR Tennessee Circle 1/8 mile on Right. S. R. No.

SUBDIVISION NAME L.N. LOT NO. 930/89 SECTION OR BLOCK NO. 16

House ( ) Mobile Home (✓) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	( )	No	(✓)	
Auto. Dishwasher	Yes	(✓)	No	( )	
Auto. Wash. Machine	Yes	(✓)	No	( )	
Site Suitable	Yes	(✓)	No	( )	

Character & Porosity of Soil Clay
Percolation Rate 4
Topography 2-6%
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area 1 ACRE

( ) Basement with Plumbing ( ) Basement without Plumbing ( ) No Basement Pump tank 1000



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Julian Bowles

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: ✓

IMPROVEMENTS PERMIT BY ~~Grad~~ David R. Hinson, Andre C. Pruen

COMMENTS: Homeowner should obtain High water alarm from Installer.

CERTIFICATE OF COMPLETION BY Andre C. Pruen DATE 8/31/88

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold