DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

4639-41-0617

PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Woodleaf
ADDRESS:
APPLICATION DATE
PROPOSED FACILITY: House
PROPOSED DESIGN FLOW (.1949): 480
DATE EVALUATED: 6-1-
LOCATION OF SITE: Lot 19
PROPERTY SIZE:
PROPERTY RECORDED:
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	pit 20	0-10	scl sbk	ss, sp, fri	Brown				.25
		10-48	c sbk	ss, sp, fri	Red/yellow Brown mottles	manganese noted			
		48-54	cl (w) sbk	ss, sp, fri	Red brown				
2	pit # 55 L	0-12	No sbk c	FR ss/sp	Red				0.3
		12-42	wk sbk cl	FR ss/sp	Red; C sap				
		42-52	MA/sl sap	FR ns/np	Br; F Rock Fragments				
3		0-7	wk sbk brn sl/fi dry ss sp						@ 2-.225
		7-15	mbk red c	fr ss sp sap	36"+				
		15-54	wk sbk cl	fr ss sp	few red ~36"			24" max	
			common white mottles						
4	1% L	0-5	mgr brn sl	fr ss sp					.3
		5-30	msbk red c	fr ss sp sap					
		30-54	wk sbk red cl	fr ss sp few red/brn/gry					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR	.25	

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Jeremy Michael
OTHER(S) PRESENT:

COMMENTS: Need to look at other pits