Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 OF 1
PIN #: 4639-41-5251
Lot #: 5
Permit #: REPAIR
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: **MOREY HERENDEEN**
Applicant: **SAME**
Address: **251 KEMP RD.**
Date Evaluated: **5/25/2012**
Proposed Facility: **SFR** Design Flow (.1949) **360 GPD** Property Size: **.87 AC**
Location of Site: **CL&T SECTION 15 LOT 5** Property Recorded: **YES**
Water Supply: [ ] Public [X] Individual [X] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 Structure/ Texture	SOIL MORPHOLOGY .1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
AB 1	6% LINEAR	0-48	C/CL,M,SBK	SS,FR	NA	48"	NA	48"+	.3
AB 2	6% LINEAR	0-25	C,M,SBK	SS,FR	NA	48"	NA	48"+	.3
		25-48	CL,M,SBK	SS,VFR					
AB 3	6% LINEAR	0-22	CL,M,SBK	SS,VFR	Y/BR CH3 @ 22"		NA		.2
		22+	CL,M,SBK	SS,FR					

Description	Initial System	Repair System
Available Space (.1945)	PS	PS
System Type(s)	G-25%	G-25%
Site LTAR	.3	.2

Other Factors (.1946): **SHALLOW REPAIR**
Soil Evaluation By: **BEN ALDRIDGE**
Others Present: **RUSSELL WILLIAMS**
Site Classification (.1948): **PS**
Site Evaluation By: **BEN ALDRIDGE**
Others Present: **RUSSELL WILLIAMS**