DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #:
COUNTY: Franklin

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ~~Johnny Craver~~ Tony Pappit
ADDRESS:
PROPOSED FACILITY: 4 bedroom PROPOSED DESIGN FLOW (.1949): 480 gpd
LOCATION OF SITE: Wildwood Cove 38
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

APPLICATION DATE
DATE EVALUATED:
PROPERTY SIZE:
PROPERTY RECORDED:

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAP CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
AB 1	LS 5%	0-5	Fill			48"			PS 0.3
		5-15	R C SBK	Fr SS SP					
		15-22	R SCL WSBK	Fr SS SP					
		22-48	R CL WSBK	Fr SS SP					
AB 2	LS 5%	0-30	R C SBK	Fr SS SP		48"			PS 0.3
		30-48	R CL WSBK	Fr SS SP					
AB 3	LS 5%	0-36	R C SBK	Fr SS SP	Chr 2 @ 22" @ 29" no mottles	22"			Drip 0.1
		36-48	R CL WSBK	Fr SS SP					
4	LS 5%	0-48	R C SBK	Fr SS SP	Chr 2 @ 33" 34" No mottles	33"			PS 0.25

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	1200 ft2	4800 ft2
System Type(s)	25% Reduction	Drip
Site LTAR	0.3	0.1

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY: M A & Assoc
OTHER(S) PRESENT:

Approved ICHD 4-5-13

COMMENTS: