VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Otts APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-16-00
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 4 Wildwood Cove PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed Dishwasher

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-17	ABK sandy c/cl few med sap fr ss sp						PS .34
	17-36	C/fsL	sap fr ss-po					
HBRD	36-69	LSkp	fr ss sp-po					
		DK Deeper						
	0-15	AB brn RC/cL fi ss sp						PS .03 >15"
	15-42	wk 6 yr cl few comm med sap fr ss sp						
	0-3	gr brn sdL						.1 .34
	3-26	wk AB-massive brn c/cl fi-vfi ss sp						
	26-42	C/LsL sap fr ss-sp po						
		Dig deeper !						
	0-11	wk AB massive brn c/cl fi-vfi						PS .3 >11"
	11-44	wk Bt/Bk 6 yr cl few med sap fr ss sp-sap						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Suitable Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


NTERS, LLC
PG 1451
23 PG 167
142'
113'
830
209'
840
3
47490 SF
825
290'
4
51250 SF
305'
84
5
46040 SF
835
602
DRIVE
825'
820
142'
830
129'
815
202'
825
820
195'