Lot 4/5 AREA

North Carolina
Department of Natural Resources and Community Development
Division of Environmental Management

P. O. Box 27687 - Raleigh, N. C. 27611

WELL ABANDONMENT RECORD

CONTRACTOR _____ REG. NO. _____

1. WELL LOCATION: (Show a sketch of the location on back of form.)
   Nearest Town: South: Mooresville, North: Troutman County IREDELL
   Wildwood Cove S.D. LOT #5 / FERN Hill Rd. Quadrangle No. 35
   (Road, Community, Subdivision, Lot No.)
2. OWNER: Crescent Resources
3. ADDRESS: P.O. Box 1003, CHAR, NC. 28201
4. TOPOGRAPHY: draw, slope, hilltop, valley, flat
5. USE OF WELL: Previous/Past WATER Source DATE: _____
6. TOTAL DEPTH: 10' DIAMETER: 2'
7. CASING REMOVED:

feet	diameter
N/A	N/A
↓	↓

8. SEALING MATERIAL:

Neat cement	Sand cement
bags of cement N/A	bags of cement N/A
gals. of water ↓	yds. of sand ↓
	gals. of water ↓

Other
Type material Clay fill
Amount 4-6 YARDS of fill


9. EXPLAIN METHOD OF EMPLACEMENT OF MATERIAL.
Well was filled with clay material in 1'to 2' lifts. + compacted until it reached original surface level. Also Bentonite Clay was used

I do hereby certify that this well abandonment record is true and exact.

M. Athanas. 1-10-2001
Signature of Contractor or (Agent) Date

WELL DIAGRAM: Draw a detailed sketch of the well showing total depth, depth and diameter of screens remaining in the well, gravel interval, intervals of casing perforations, and depths and types of fill materials used.

HAND DUG WELL



- 2' DIAMETER
- 10' IN Depth
- STONE CASING
- WELL WAS FILLED USING 1+2' lifts + then Compacted until it reached surface level.
- Also Bentonite clay was added.

Submit original to the Division of Environmental Management, one copy to the Driller, and one copy to the Owner.